


Ans-9


BUILDING CERTIFICATE


The school building of Principal DAV Public School Greyoh, Sub Tehsil Tihra Distt. Mandi H.P. was inspected by me with the concerned Junior Engineer. As per report of the Junior Engineer this building has neither been designed nor constructed by this office. No earthquake resistant norms have been adopted for this building. No structural drawings approved by the competent Government Agency have been produced. The structure is a Non Engineering structure. Hence the structural safety of this building cannot be ensured specially from Earthquake point of view. This building has been constructed in the year (Block-I 2003 to 2006) (Block II 2008 to 2011) (Block III 2011 to 2018) . The department will not be responsible for any type of loss of life and property etc., if this structure fails under any circumstances. However as per visual inspection the building has been found to be safe for the session 2019-2020.


Dated:- 21-01-2019

Place:- Tihra


Junior Engineer,
Tihra Section,
HPPWD Tihra


Assistant Engineer,
Tihra Sub Division
HPPWD Tihra


Executive Engineer,
B & R Division,
HP.PWD. Dharmapur


Principal
D.A.V Public School Greyoh
Sarkaghat Distt. Mandi (H.P.)