

HPPWD - DHR / DAVPS - G / BSC - 22-23/01

BUILDING CERTIFICATE

The school building of DAV Public School Greyoh, Sub. Tehsil Tihra, Dharampur, Distt. Mandi HP was inspected by me with the concerned Junior Engineer. As per report of the Junior Engineer this building has neither been designed nor constructed by this office. No earthquake resistant norm has been adapted for this building. No structure drawing approved by the complete Government Agency has been produced. The structure is a Non Engineering structure. Hence the structural safety of this building cannot be ensured specially from Earth quick point of view. This building has been constructed in the year (block-I 2003 - 2006, Block - II 2008 - 2011, Block - 3 2011 - 2018). The department will not be responsible for any type of loss of life and property etc., if this structure fails under any circumstances. However as per visual inspection the building has been found to be safe for session 2022-23.

Dated: 21.01.2022

Place: Greyoh
Junior Engineer
Tihra Section
HPPWD Tihra

Assistant Engineer
Tihra Sub. Division
HPPWD Tihra

9/5

Executive Engineer
B & R Division,
HPPWD Dharampur